IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

I hereby certify that this correspondence is being electronically filed with the United States Patent and Trademark Office on May 12, 2010 at or before 11:59 p.m. Pacific Time under the Rules of 37 CFR § 1.8.

Signature Burchfield

U.S. Patent No.

: RE40657

Confirmation No. 2547

Issued

: March 10, 2009 : Dong Tack Suh

Inventor(s)
Application No.

: 10/812,342

Filed

: March 29, 2004

Title

: PULL PIN ASSEMBLY FOR CANOPY

REQUEST FOR CERTIFICATE OF CORRECTION

Office of Certificates of Correction Commissioner for Patents P.O. Box 1450

P. O. Box 7068

Pasadena, CA 91109-7068

May 12, 2010

Alexandria, VA 22313-1450

Commissioner:

Submitted herewith is a copy of a proposed Certificate of Correction for the above-referenced patent. The errors are identified in detail in the proposed certificate, and the corresponding text in the application is located as follows:

Location in Patent

Location in Application

PTO errors:

Column 8, Claim 22, line 34

Amendment dated September 24, 2008,

page 7, old claim 38, line 9

Applicant errors:

Column 7, claim 19, line 39

Amendment dated September 24, 2008,

page 5, old Claim 23, line 1

U.S. Patent No. RE40657

Applicant's error was unintentional and inadvertent, and was made in good faith through oversight. Correction is accordingly requested under 35 U.S.C. § 255, and the statutory fee of \$100.00 is submitted herewith. Any deficiency or overpayment should be charged or credited to Deposit Account No. 03-1728. Please show our docket number with any credit or charge to our Deposit Account.

Correction of applicant's error does not constitute new matter or require reexamination. Approval of this certificate is respectfully requested.

Respectfully submitted,

CHRISTIE, PARKER & HALE, LLP

By

Tiffany A Parche

626/705 0000

TP/smm

Enclosures:

Certificate of Correction

TP PAS893581.1-*-05/12/10 1:51 PM

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION		
PATENT NO. : APPLICATION NO.: ISSUE DATE : INVENTOR(S) :	RE40657 10/812,342 March 10, 2009 Dong Tack Suh	Page of
It is certified the is hereby corrected	nat an error appears or error I as shown below:	s appear in the above-identified patent and that said Letters Patent
In the Claims		
Column 7, Claim 1	19, line 39	Before the word "resilient" insert the word the
Column 8, Claim 2	22, line 34	After the word "bosses" delete the word "therein" and insert the word thereon

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Christie, Parker & Hale, LLP P.O. Box 7068 Pasadena, CA 91109-7068

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.